


Signal lamp, LED green H2

Lamps for show of the detected level limit.

Selection of lamp function


Short circuit bridge to be connected in required position.




001-0226

Glue on of the level limit symbols

After the adjusting of the lamp function glue on the respective symbol next to the lamp.





001-0228



Full indication

Lamp shines, if bulk goods are existing.

Measuring blade has stopped („full“)



Empty indication

Lamp shines, if bulk goods are missing.

Measuring blade is rotating („empty“)

